



DIVING SYSTEMS INTERNATIONAL, Inc.

425 Garden Street

Santa Barbara, California 93101



Telephone (805) 965-8538, Fax (805) 966-5761

**Bulletin No. 3 1998: Change to Product.
14 December, 1998**

Subject: Regulator Change

**Products Affected:
Kirby Morgan KMB 18B Band
Mask**

As of January 1, 1999
the Kirby Morgan KMB 18B Band Mask, Part
numbers 500-025, 500-026, will ship as standard
with the DSI large tube *SuperFlow 350* regulator,
Part number 505-069 (currently standard on
the SL-27). This replaces the small tube regulator,
Part number 505-027. The KMB 18A Band
Mask will continue to ship standard with the
small tube regulator.



The small tube fiberglass mask frame, **Part number 520-055**,
will still be available as a replacement part. The KMB 28 Band
Mask frame, **Part number 520-096**, will continue to support
the small tube regulator.